

## Pavement Evaluation Coring and Condition Data

Cored By: UNIVERSAL		Date: 05/02/18		Page 1 of 1		Typical Section: 1 of 1												
Project No.: 439468-1-52-01		Name: SR115				Lanes: 6												
State Road No.: SR115		From: Deerwood Park Intersection				Shoulders												
County: DUVAL		To:				Inside:												
Section No: 72040000		Beg MP: 4.014		End MP: 4.624		Length: 0.610		Outside:										
Core Number	Mile Post	Lane	Wheel Path	Pavement Layer				Core Length	Base Type	Crack				Pavement Condition	Rut Depth (inches)	Cross Slope (ft per 6 ft.)	Slope Direction (in / out)	Comments:
				FC3	S	T2	T1			Depth	Type	Class	Extent					
1	4.177	R1	Y	1.3	2.7	1.5	2.5	8.0	LR	0.8	B	IB	L	P				SR
2	4.325	R1	N	1.2	2.1	1.8	2.6	7.7	LR	0.7	B	IB	L	P				SR
3	4.137	R3	Y	0.8	3.0			3.8	ABC = 6.2					P				SR
4	4.303	R3	N	1.3	2.8			4.1	ABC = 7.3					P				SR
5	4.193	RTRTTL	Y	1.1	4.2			5.3	ABC = 6.8					P				
6	4.177	RTLTTTL	Y	1.7	4.3			6.0	ABC = 5.5					P				SR
7	4.137	OR	N	1.1				1.1	ABC = 4.1					P				SR
8	4.193	OR	N	1.5				1.5	ABC = 4.5					P				
9	4.303	OR	N	1.3				1.3	ABC = 5					P				SR
10	4.177	L1	N	1.3	4.1			5.4	ABC = 6.3					P				SR
11	4.351	L1	N	1.5	3.7	1.9	3.2	10.3	LR					P				SR
12	4.364	L4	Y	1.5	3.0			4.5	ABC = 6.7					P				SR
13	4.351	LTLTTTL	Y	1.8	6.8	1.8	2.9	13.3	LR					P				SR
14	4.364	OL	N	1.5				1.5	ABC = 6					P				SR
15	-	-	N	1.7				1.7	LR					F				Svc Rd. at MP 4.163, SR
16	4.258	TO	N	1.2	1.3			2.5	LR	2.5	B	IB	L	P				Deerwood Park
Remarks: SR = slightly raveled																		