

## Pavement Evaluation Coring and Condition Data

Cored By: UNIVERSAL		Date: 05/29/19		Page 1 of 3		Typical Section: 1 of 3												
Project No.: 438928-2-52-01		Name: SR202/JTB				Lanes: 6												
State Road No.: SR202		From: EAST OF I-95				Shoulders												
County: DUVAL		To: US1				Inside: Curb & Gutter												
Section No: 72292000		Beg MP: 0.000		End MP: 0.373		Length: 0.373												
Outside: Curb & Gutter																		
Core Number	Mile Post	Lane	Wheel Path	Pavement Layer				Core Length	Base Type	Crack				Pavement Condition	Rut Depth (inches)	Cross Slope (%)	Slope Direction (in / out)	Comments:
				FC125	SP125	S1						Depth	Type					
1	0.370	R1	N	1.8	2.6			4.4	LR					F				
2	0.093	R3	O	1.8	3.1			4.9	ABC=7.0					F				
3	0.168	R3	N	1.5	3.5			5.0	ABC=6.7					F				
4	0.219	R3	O	1.3	3.7			5.0	ABC=8.7					F				
5	0.331	R3	O	1.1	3.4			4.5	ABC=8.5					F				
6	0.129	L1	I	1.5	3.0			4.5	ABC=10.9					F				
7	0.038	RAMP	O	1.8	3.5			5.3	ABC=6.7					F				Ramp from NB US 1 to EB JTB
8	0.143	RLTTL1	N	1.5	2.7			4.2	LR=7.3					F				EB JTB to NB Bonneval
9	0.157	RLTTL2	N	1.4	3.5			4.9	LR					F				EB JTB to NB Bonneval
10	0.186	-	N	1.4	3.5			4.9	LR					F				intersection of US1/SR202
11	0.257	LLTTL1	N	1.1	2.8			3.9	LR					F				WB JTB to SB Bonneval
12	0.215	LLTTL1	O	1.2	2.2	0.7		4.1	LR					F				WB JTB to SB Bonneval
13	0.031	LLTTL1	N	1.4	2.5			3.9	LR					F				WB JTB to SB US 1
<b>Bonneval Rd.</b>																		
14	175'	L1	I			2.5		2.5	LR					F				ft from SR202
15	155'	RRTTL1	N			3.0		3.0	LR					F				ft from JTB, NB Bonneval to EB JTB
16	50'	RRTTL2	O	1.5	0.9			2.4	LR					F				ft from JTB/ * /NB Bonneval to EB JTB
Remarks: SR=SLIGHT RAVELLING / *=DEPRESSION/PATCH NEAR CORE (60' PAVEMENT CHANGE)																		
I = Inside, O= Outside																		

## Pavement Evaluation Coring and Condition Data

Cored By:		UNIVERSAL		Date:		05/29/19		Page		2 of 3		Typical Section:		2 of 3										
Project No.:		438928-2-52-01		Name:		US1		Lanes:		4		Shoulders												
State Road No.:		US1		From:		South of SR202						Shoulders												
County:		DUVAL		To:		N of Mustang Rd						Inside:		2' paved										
Section No:		72070000		Beg MP:		11.998		End MP:		12.220		Length:		0.222										
														Outside: 5' paved										
Core Number	Mile Post	Lane	Wheel Path	Pavement Layer								Core Length	Base Type	Crack				Pavement Condition	Rut Depth (Inches)	Cross Slope (%)	Slope Direction (in/out)	Comments:		
				FC6	FC125	SP125	FC2	ARMI	S2	S1	T1			BIND	Depth	Type	Class						Extent	
17	12.016	RLTTL	I	1.2		5.1							6.3	ABC=9.6					P					SR, NB US1 to south Park-n-Ride lot entrance
18	12.176	LLTTL	N	0.8		2.6	0.9				1.7		6.0	ABC=5.3					P					SR, SB US1 to EB JTB
19	12.061	L1	N	1.2		2.1		0.5			4.8		8.6	CONC					P					SR
20	12.195	L2	N	1.1		2.3		0.5				2.0	5.9	CONC	1.1	B	IB	L	P					SR/separated at 1.1"/grinding
21	12.078	L2	O		1.2	2.2						1.9	5.3	CONC					F					
22	12.060	L2	O	0.8		2.8		0.5				1.7	0.6	6.4	LR				P					SR/BOTTOM UP CRACK TO ARMI 1.7"
23	12.195	OL	N	0.6		1.8							2.4	RAP					F					
24	12.003	CO	N	1.1		2.3	0.7				3.2		7.3	LR					P					BOTTOM UP TO 2.3"
25	12.011	RRTTL	O	1.0		3.0			2.3				6.3	LR					P					SR, NB US1 to EB JTB
26	12.059	RRTTL	I		1.6	0.9			3.2				5.7	LR					F					BOTTOM UP TO 1.6", NB US1 to EB JTB
27	12.056	RLTTL	I		1.5	3.5							5.0	ABC=8.0					F					NB US1 to south Park-n-Ride lot entrance
28	12.170	RLTTL	N	0.9		2.8						3.2	6.9	LR	0.2	B	IB	L	P					SR, NB US1 to north Park-n-Ride lot entrance
29	12.195	RLTTL	O	1.0		2.0						2.8	5.8	LR					P					SR, NB US1 to north Park-n-Ride lot entrance
30	12.222	CO	N	0.8		2.0						1.0	1.7	5.5	LR=7.8	5.5	B	II	L	P				SR
31	12.236	LRTTL	O	1.1		3.3						1.5	5.9	LR					P					SR, SB US1 to north Park-n-Ride lot entrance
32	12.160	LLTTL1	O	1.1		2.3							3.4	ABC=10.4					P					SR, SB US1 to EB JTB
33	12.127	LLTTL2	I	0.9		2.9					4.0	2.2	10.0	LR					P					SR, SB US1 to EB JTB
34	12.115	LLTTL1	N	1.1		2.4					2.8		6.3	ABC=9.5					P					SR, SB US1 to EB JTB
35	12.111	L2	N	1.1		2.6		0.5				2.0	6.2	CONC					P					SR
36	12.089	-	N		1.5	2.3		0.5			0.6		1.2	6.1	LR				P					middle of intersection of US-1/JTB

Remarks: SR=SLIGHT RAVELLING  
I = Inside, O= Outside

### Pavement Evaluation Coring and Condition Data

Cored By: UNIVERSAL	Date: 05/29/19	Page: 3 of 3	Typical Section: 3 of 3
---------------------	----------------	--------------	-------------------------

Project No.: 438928-2-52-01	Name: SR202/JTB FROM EAST OF I-95 TO US1
-----------------------------	--

Core Number	Mile Post	Lane	Wheel Path	Pavement Layer						Core Length	Base Type	Crack				Pavement Condition	Rut Depth (inches)	Cross Slope (%)	Slope Direction (in/out)	Comments:
				← top								Depth	Type	Class	Extent					
				FC6	SP125															
37	12.060	OL	N	1.2	1.8				3.0	RAP					F			SB US 1		
<b>Park and Ride</b>																				
38	-	PA	N		1.9				1.9	LR					P			SR		
39	-	PA	N		1.4				1.4	LR					P			SR		
40	-	PA	N		1.7				1.7	LR	1.7	B	II	M	P			SR / SPALLING		

Remarks: SR=SLIGHT RAVELLING  
 PA = Parking Area of Park-n-Ride lot