



## Pavement Evaluation Coring and Condition Data

Cored By: UNIVERSAL		Date: 10/08/19		Page 2 of 2		Typical Section: 2 of 2														
Project No.: 445418-1-52-01		Name: SR228 (E Adams St)				Lanes: 2														
State Road No.: SR228		From: Main St				Shoulders														
County: Duval		To: N Liberty St				Inside: curb and gutter														
Section No: 723000001		Beg MP: 0.000		End MP: 0.317		Length: 0.317														
Outside: curb and gutter																				
Core Number	Mile Post	Lane	Wheel Path	Pavement Layer					Core Length	Base Type	Crack				Pavement Condition	Rut Depth (inches)	Cross Slope (%)	Slope Direction (in / out)	Comments:	
				FC6	FC3	SP125	S1	T1			Depth	Type	Class	Extent						
13	0.150	R1	N	0.8	-	1.0	0.7	-	-	2.5	Brick	2.5	B	II	M	P				light raveling
14	0.295	R1	N	-	1.2	-	1.4	0.6	-	3.2	Brick	-	-	-	-	P				light raveling
15	0.050	R2	I	0.9	-	0.8	-	1.5	-	3.2	Conc.	1.2	B	III	M	P				light raveling/shoving/spalling
16	0.250	R2	O	-	1.2	-	-	1.9	-	3.1	Brick	3.1	B	II	M	P				light raveling/spalling
17	0.150	IR	N	1.5	-	-	0.6	1.9	-	4.0	Brick	-	-	-	-	F				light raveling
18	0.295	IR	N	-	1.4	-	-	-	-	1.4	Brick	-	-	-	-	F				
19	0.050	OR	N	1.1	-	0.9	-	-	-	2.0	ABC=7.0"	2.0	B	III	M	P				shoving/ABC=T2 Mix
20	0.250	OR	N	-	1.3	-	-	2.5	-	3.8	Brick	3.8	B	II	M	P				
21	0.094	TO	N	1.3	-	0.5	-	1.0	-	2.8	Brick	2.8	B	II	M	P				
22	0.241	TO	N	2.0	-	1.2	-	-	-	3.2	Brick	-	-	-	-	F				

Remarks: Pavt. Change @ MP 0.245