

## Pavement Evaluation Coring and Condition Data

Cored By: UNIVERSAL				Date: 10/09/19		Page 1 of 3		Typical Section: 1 of 1												
Project No.: 445343-1-52-01				Name: SR126 (EMERSON ST)				Lanes: 4												
State Road No.: SR126				From: US1				Shoulders												
County: DUVAL				To: SPRING PARK RD				Inside: curb and gutter												
Section No: 72015000				Beg MP: 1.066		End MP: 1.640		Length: 0.574		Outside: curb and gutter										
Core Number	Mile Post	Lane	Wheel Path	Pavement Layer						Core Length	Base Type	Crack				Pavement Condition	Rut Depth (inches)	Cross Slope (%)	Slope Direction (in/out)	Comments:
				FC6	FC125	SP125	T2	BIND	ST			Depth	Type	Class	Extent					
1	1.181	R1	I	1.5		1.5				3.0	LR	3.0	B	II	S	P				
2	1.300	R1	O	1.5		1.4		1.4		4.3	LR=5.7	4.3	B	IB	L	P				light raveling
3	1.483	R1	I	1.5		1.6				3.1	LR=5.8	1.5	C	III	S	P				light raveling/spalling/pumping
4	1.557	R1	I	1.6		1.7				3.3	LR	3.3	C	III	S	P				light raveling/spalling/pumping
5	1.114	R2	O	1.5		1.7				3.2	LR	3.2	B	II	M	P				light raveling
6	1.247	R2	O	1.5		1.6				3.1	LR=7.4	3.1	B	II	M	P				light raveling/spalling
7	1.556	R2	O	1.3		1.4				2.7	LR=7.2	2.7	C	II	S	P				light raveling/spalling
8	1.622	R2	I	1.4		1.2				2.6	LR	2.6	B	II	M	P				light raveling
9	1.120	L1	N		1.3					1.3	LR=7.9					P				moderate raveling
10	1.250	L1	I	1.4		1.5				2.9	LR	2.9	B	II	M	P				light raveling
11	1.550	L1	I	1.2		2.1				3.3	LR	3.3	B	II	M	P				light raveling
12	1.600	L1	I	1.5		1.4				2.9	LR=4.7	1.5	B	II	M	P				light raveling
13	1.186	L2	O	1.5		1.9				3.4	LR=9.1	3.4	B	II	L	P				
14	1.300	L2	I	1.6		1.2				2.8	LR	2.8	B	IB	L	P				
15	1.479	L2	O	1.2		1.5				2.7	LR	2.7	C	III	S	P				light raveling/spalling/delaminated
16	1.537	L2	O	2.1		1.2	0.3		0.5	4.1	LR=7.6	4.1	C	III	M	P				light raveling/spalling/shoving
17	1.139	LLTTL1	I	1.7		1.0				2.7	LR					F				
18	1.130	LLTTL2	I	1.7		1.8				3.5	LR	3.5	C	III	S	P				spalling/pumping
19	1.200	LLTTL	N	1.4		1.5				2.9	LR					F				light raveling
20	1.306	LLTTL	N	1.0		2.0				3.0	LR					F				light raveling

Remarks: Patch in R1 at MP 1.520, 1.585, and MP 1.605 & in L1 at 1.320. Pavement change in all lanes MP 1.112-1.135  
 CC = Center Crown



