

Pavement Evaluation Coring and Condition Data

Cored By: UNIVERSAL	Date: 02/01/21	Page 1 of 1	Typical Section: 1 of 1
Project No.: 447122-1	Name: SR128(San Juan) From SR111(Cassat) To SR211(Herschel)		Lanes: 4
State Road No.: SR128	From: SR111(Cassat Ave)		Shoulders
County: Duval	To: SR211(Herschel Ave)		Inside: -
Section No: 72017000	Beg MP: 1.494	End MP: 2.500	Length: 1.006
			Outside: curb and gutter

Core Number	Mile Post	Lane	Wheel Path	Pavement Layer					Core Length	Base Type	Crack				Pavement Condition	Rut Depth (inches)	Cross Slope (%)	Slope Direction (in / out)	Comments:
				← top	FC6	SP125	T2	ST			Depth	Type	Class	Extent					
1	1.632	R1	O	1.4	1.1	0.3	0.4	3.2	LR=9.1	3.2	B	II	M	P				light raveling	
2	1.925	R1	O	1.3	1.5			2.8	LR	2.8	B	II	M	P				light raveling	
3	1.548	R2	N	1.1	1.6			2.7	LR=9.3	2.7	B	II	M	P				light raveling	
4	1.842	R2	I	1.1	1.1			2.2	LR	2.2	B	II	M	P				light raveling	
5	1.558	L1	O	1.5	1.2			2.7	LR	2.7	B	II	M	P				light raveling	
6	1.876	L1	N	1.0	1.9			2.9	LR=9.5	2.9	B	III	M	P				severe raveling, spalling	
7	1.579	L2	N	1.1	1.9			3.0	LR	3.0	B	III	M	P				severe raveling, IWP	
8	1.666	L2	N	1.0	1.6			2.6	LR	2.6	B	II	M	P				light raveling	
9	1.778	L2	O	1.0	1.6			2.6	LR	2.6	B	II	M	P				light raveling	
10	2.021	L2	O	1.0	1.8			2.8	LR=9.2	2.8	B	II	M	P				light raveling	
11	1.706	LPA	N	1.2	2.0			3.2	LR					F					
12	1.864	RTO	N	1.3		0.7		2.0	LR					P				severe raveling	
13	1.614	LTO	N	1.2		1.7	0.5	3.4	LR					P				severe raveling	
14	1.970	RLTTL	N	1.1	3.1	0.5	0.5	5.2	LR					F				light raveling	
15	1.775	LTTL	N	2.0	1.3	0.4	0.5	4.2	LR					P				light raveling, dip (OWP)	

Remarks: Pavement change all lanes: MP 1.730, 1.759 / R2 1.579: patch, severe raveling, spalling, dip OWP(2.59'), patch R1: 1.993

Pavement Evaluation Coring and Condition Data

Cored By: D2MR		Date: 08/26/20		Page 1 of 1																	
Project No.: 440552-1-52-01		Name: San Juan Ave. From Roosevelt Blvd. to Herschel St.										Lanes: 4									
State Road No.: SR128		From: SR 15/ US 17 Roosevelt Blvd.										Shoulders									
County: Duval		To: Herschel St.										Inside: N/A									
Section No: 72017000		Beg MP: 2.096		End MP: 2.500		Length: 0.404		Outside: C&G													
Core Number	Mile Post	Lane	Wheel Path	Pavement Layer							Core Length	Base Type	Crack				Pave Condition	Rut Depth (Inches)	Cross Slope (ft. per 6 ft.)	Slope Direction (I=In / O=out)	Comments:
				FC 6	SP 12.5	Type 1	Binder	Type 1	Type 2	Binder			Depth	Type	Class	Extent					
1	2.196	R1	IWP	1.4	2.4					1.6	5.4	LR=3.8	4.0	B	II	M	P				LR, STA 15+00
2	2.453	R2	OWP	1.7	1.9						3.6	LR	3.6	B	II	L	P				LR, Separated @ 1.7" ,STA 28+50
3																					Omitted in field
4	2.329	L1	OWP	1.5	3.2						4.7	LR	3.1	B	II	M	P				LR, STA 22+95
5	2.439	L1	OWP	1.0	1.8					0.6	3.4	LR=6.8	3.4	B	II	M	P				MR, STA 28+50
6	2.167	L2	OWP	1.5	2.4					1.1	5.0	LR					P				LR, STA 14+40
7	2.125	LLTTL	IWP	1.6					2.3	1.2	5.1	LR	5.1	B	II	M	P				MR, Spalling, Seperated @ 1.8", STA 12+20
8	*	L1	N	1.2	0.6	0.6	1.7	1.3	0.9		6.3	LR					P				LR
Remarks: LR= Lightly Raveled MR= Moderately Raveled * Core was cut 154' East of Herschel St. intersection.																					