										nent Evaluation Coring and Condition Data											
Cored By: D2 Materials							Date:									Typica	Section: 1	of 1			
Project No.: 209537-9																	Lanes:				
State Road No.: SR 201(US301)								From: Bullnose of SR 201(US301A)											Shoulders		
	County: Duval									To: 530' West on Brandy Branch Rd.											Seperator
Se	ection No:	1	721450000					Beg MP:	0.50	00 E		nd MP: 0.550			Length:		0.050		Outside: 5'	5'	
Cor	Mile Post	Lane	Wheel Path	<del></del>	Тор	Pavement Layer				Core	B.	Crack				C P	~ R	Cro	Slop		
Core Number				FC 12.5	SP 12.5					re Length	Base Type	Depth	Туре	Class	Extent	Pavement Condition		Cross Slope (%)	Slope Direction ( in / out )	Comments:	
1	270' W	LLTTL	ı	1.8	5.7					7.5	LR					G					
2	530' W	L1	0	1.8	6.0					7.8	LR					G					
3	530' W	OL	N	1.4	4.2					5.6	LR					G					
4	530' W	TO	N	1.5	3.5					5.0	LR					G				Turn out into Love's parking lot	
5	200' W	RRTTL	0	1.7	6.2					7.9	LR=10.9					G					
6	200' W	OR	N	1.7	3.4					5.1	LR					G					
7	200' W	RLTTL	I	1.5	5.7					7.2	LR					G					
8	100' W	R1	N	1.4	5.8					7.2	LR					G					
+																					
_																					
7																					
+																					
$\dashv$																					