

Pavement Evaluation Coring and Condition Data

Cored By: CSI Geo, Inc.		Date: 06/12/24		Page 1 of 1		Mainline	
Project No.: 209697-5		Name: SR 13 (Hendricks Ave)		Lanes: 2 lanes w/ 11' Pvd Med			
State Road No.: SR 13		From: San Marco Blvd		Shoulders			
County: Duval		To: Prudential Drive		Inside: N/A			
Section No: 72160000		Beg. MP: 12.726		End MP: 13.709		Length: 0.983	
Outside: 4' Pvd w/ C&G							

Core Number	Mile Post	Lane	Wheel Path	Pavement Layer						Core Length	Base Type	Crack				Pave Condition	Rut Depth (inches)	Cross Slope (ft. per 6 ft.) %	Slope Direction (I=in / O=out)	Comments:
				FC 12.5	SP 12.5	T-2	T-1	T-2	ST			Depth	Type	Class	Extent					
1	13.665	L1	O	1.5	2.7	1.5	1.3			7.0	LR	2.6	B	II	L	P				Slightly Raveled
3	13.547	L1	N	1.6	3.3					4.9	ABC=7.8					G				
4	13.467	L1	O	1.7	2.0					3.7	SSG	3.7	B	II	L	P				
5	13.317	L1	O	1.7	2.1	2.1				5.9	SSG	1.7	B	II	L	F				
7	13.252	L1	O	1.4	2.4					3.8	BRCK	3.8	B	II	M	P				
9	12.859	L1	O	1.2	1.8	0.8			0.4	4.2	BRCK	4.2	B	II	S	P				
11	12.859	R1	O	1.1	1.4	1.4			0.5	4.4	BRCK	4.4	B	II	M	P				
13	12.974	R1	O	1.4		1.3				2.7	BRCK					P				
15	13.225	R1	N	1.5	1.8	2.2	0.8	3.3		9.6	LR	2.4	B	II	M	P				
17	13.469	R1	O	1.5	1.0	3.4				5.9	BRCK	5.9	B	II	M	P				
19	13.630	R1	O	2.0		1.3	1.5			4.8	BRCK	4.8	B	III	M	P				
2	13.665	OL	N	1.4	3.5					4.9	ABC=10.5					F				
6	13.317	OL	N	1.4	5.0					6.4	ABC=7.2					F				
10	12.859	OL	O	1.5	3.4					4.9	ABC=7.7					F				
12	12.859	OR	N	1.6	1.8					3.4	ABC=6.5					F				
18	13.469	OR	N	1.7	2.9					4.6	ABC=4.0					F				
8	13.020	LTO	N	2.1	2.5					4.6	ABC=2.0					F				
16	13.412	RTO	N	2.4			1.0			3.4	LR	1.7	B	II	L	F				
14	12.974	CTL	N	1.7	1.8					3.5	ABC=11.2					F				
20	13.630	CTL	N	1.9	2.0	1.8				5.7	LR	2.5	B	IB	L	P				

Remarks: _____

