Pavement Evaluation Coring and Condition Data

Cored By:	UNIVERSAL	Date:	06/13/24	Page 1 of 1	Typical Section:	1 of 1	
Project No.:	213273-8	Name:	I-95 (SR9) From Clark Road To South of SR104		Lanes:	6	
State Road No.:	SR 9	From:	Clark Road		Shoulders		
County:	Duval	To:	South of SR104		Inside:	12' PAVED	
Section No:	72020000	Beg MP:	9.600	End MP: 10.567	Length:	0.967	Outside: 10' PAVED

Core Number	Mile Post	Lane	Wheel Path	Pavement Layer (top →) FC125	SP125					Core Length	Base Type	Crack Depth	Crack Type	Crack Class	Crack Extent	Pavement Condition	Rut Depth (inches)	Cross Slope (%)	Slope Direction (in / out)	Comments:
1	9.630	IR	N	1.3	1.7					3.0	LR					F				
2	10.200	IR	N	1.0	1.6					2.6	LR					F				
3	9.900	OR	N	0.7	1.4					2.1	LR					F				
4	10.500	OR	N	0.7	1.6					2.3	LR					F				
5	9.900	IL	N	1.3	1.2					2.5	LR					F				
6	10.500	IL	N	2.1	1.0					3.1	LR					F				
7	9.700	OL	N	0.7	1.1					1.8	LR					F				
8	10.200	OL	N	0.5	1.2					1.7	LR					F				

Remarks: