

Pavement Evaluation Coring and Condition Data																									
Cored By: UNIVERSAL					Date: 04/16/25				Page 1 of 2				Mainline												
Project No.: 208819-2-52-01					Name: SR10(US90A)ATLANTIC BLVD															Lanes: 4 / 6					
State Road No.: SR10					From: Beacon Point Dr															Shoulders					
County: Duval					To: Brookview Dr															Inside: Curb and gutter					
Section No: 72100001					Beg MP: 0.000				End MP: 0.396				Length: 0.396				Outside: 2' paved								
Core Number	Mile Post	Lane	Wheel Path	<div><div>← top</div>Pavement Layer</div>								Core Length (in.)	Base Type	Crack				Pavement Condition	Rut Depth (inches)	Cross Slope (%)	Slope Direction (in / out)	Comments:			
				FC6	SP125	WC	S	T1	BIND					Depth (in.)	Type	Class	Extent								
1	0.075	R1	N	1.5	1.1	1.2		3.0			6.8	LR					F			curve, light raveling					
2	0.189	R1	I	1.8	2.8						4.6	LR=12.3"					F			light raveling					
3	0.101	R2	O	1.3	3.5						4.8	LR=24.2"					F			curve					
4	0.022	R3	I	2.5	3.2						5.7	LR	2.0	B	II	L	P			light raveling					
5	0.312	R3	O	1.7	1.2		1.6	0.6			5.1	LR=9.9"					F			light raveling					
6	0.056	L1	I	1.7	2.0			2.5			6.2	LR	0.8	B	II	L	P			light raveling					
7	0.252	L1	N	1.3	2.4			0.5	1.3		5.5	LR=7.5"					F			light raveling					
8	0.049	L2	O	2.0	3.8		3.3				9.1	LR=10.3"					F			light raveling					
9	0.146	L2	N	1.6	2.7			1.6	1.6		7.5	LR					F			light raveling					
10	0.350	L3	O	1.7	3.1						4.8	LR=18.2"	1.0	B	IB	L	P			light raveling					
11	0.111	IR	N	1.8	3.4						5.2	LR					F			curve					
13	0.101	OR	N	1.4	3.6						5.0	LR					F			curve					
14	0.312	OR	N	1.7	3.8						5.5	LR					F								
15	0.350	OL	N	1.8	3.0						4.8	LR					F								
16	0.111	RRTTL1	N	1.3	4.0						5.3	LR					F			curve					
17	0.049	RRTTL3	O	1.5	3.1						4.6	LR					F			curve					
18	0.359	RLTTL1	O	1.5	3.0						4.5	LR					F								
19	0.253	RLTTL2	N	1.5	3.0						4.5	LR					F			light raveling					
20	0.206	LLTTL1	O	1.5	3.7						5.2	LR					F			light raveling					
Remarks: Pavement change all lanes: MP 6.818, MP 7.520																									
Dip OWP L3: MP 6.725, 6.945, & MP 7.300																									

Pavement Evaluation Coring and Condition Data																							
Cored By: UNIVERSAL				Date: 04/16/25				Page 2 of 2				Mainline											
Project No.: 208819-2-52-01				Name: SR10(US90A)ATLANTIC BLVD																Lanes: 4 / 6			
State Road No.: SR10				From: Beacon Point Dr																Shoulders			
County: Duval				To: Brookview Dr																Inside: Curb and gutter			
Section No: 72100				Beg MP: 0.000				End MP: 0.396				Length: 0.396				Outside: 2' paved							
Core Number	Mile Post	Lane	Wheel Path	Pavement Layer							Core Length (in.)	Base Type	Crack				Pavement Condition	Rut Depth (inches)	Cross Slope (%)	Slope Direction (in / out)	Comments:		
				FC6	SP125	WC	S	T1	BIND				Depth (in.)	Type	Class	Extent							
21	6.574	R1	N	1.5	1.4			0.8			3.7	LR					F				light raveling		
22	6.850	R1	N	0.6	1.7						2.3	ABC=8.0"	0.2	B	III	L	P				light raveling, spalling		
23	7.100	R1	O	1.4	1.4				2.0		4.8	LR=9.5"	4.8	B	III	M	P				light raveling, spalling		
24	7.400	R1	O	1.7	0.9			1.2			3.8	LR	3.8	B	III	M	P				light raveling, spalling		
25	6.627	R3	N	1.5	5.2			0.4			7.1	LR=7.6"					F				light raveling		
26	6.963	R3	O	1.1	0.9			2.0			6.1	LR	2.8	B	III	M	P				spalled to structural, separated at 2.6", grinding, bump		
27	7.281	R3	O	1.1	1.5				1.4		4.0	LR	4.0	B	II	M	P				light raveling, spalling		
28	7.500	R3	I	1.5	1.3				1.0		3.8	LR	2.0	B	II	L	P				light raveling, spalling		
29	6.588	L1	N	1.5	1.7						3.2	ABC=8.3"					F				light raveling		
30	6.955	L1	I	1.4	1.5						2.9	ABC=7.6"	2.4	B	II	L	P				light raveling, spalling, patch OWP		
31	7.287	L1	I	1.4	1.6			1.4			4.4	LR	4.4	B	III	L	P				light raveling, spalling		
32	7.500	L1	N	2.0	1.3			3.0			6.3	LR					P				light raveling		
33	6.550	L3	O	1.1	2.8			0.8			4.7	LR					F						
34	6.835	L3	O	1.9	1.4				1.2		4.5	LR	1.9	B	III	M	P				moderate raveling, spalling, near storm inlet		
35	7.100	L3	I	1.6	1.4				1.2		4.2	LR=11.3"	4.2	B	II	M	P				light raveling		
36	7.400	L3	N	1.3	1.3						2.6	FLOWFILL	2.6	B	II	M	P				light raveling, spalling, flow fill=22.0(recovered)		
37	7.274	RLTTL	N	1.8	1.2						3.0	ABC=7.0"					F						
38	6.799	RTO	N	1.9				1.4	1.2		4.5	LR					F						
39	7.456	LLTTL	O	1.7	0.8						2.5	ABC=7.5"					F						
40	7.376	LTO	N	1.4					1.2		2.6	LR					F						

Remarks: Pavement change all lanes: MP 6.818, MP 7.520
Dip OWP L3: MP 6.765, MP 6.945, & MP 7.300