Pavement Evaluation Coring and Condition Data

Cored By:	UNIVERSAL	Date:	07/21/21	Page 1 of 4		Typical Section: 1 of 3	
Project No.:	210673-3-52-01	Name:	SR5(US17) From Lippizan Court To GA State Line			Lanes: 2	
State Road No.:	SR5	From:	Lippizan Court			Shoulders	
County:	Nassau	To:	GA State Line			Inside: -	
Section No:	74020000	Beg MP:	11.415	End MP: 13.375	Length: 1.960	Outside: 4' paved	

Core Number	Mile Post	Lane	Wheel Path	Pavement Layer (top) FC95	SP125	S1	FC2	T1	T2	CRL	T2	T1	BIND	ST	Core Length	Base Type	Crack Depth	Crack Type	Crack Class	Crack Extent	Pavement Condition	Rut Depth (inches)	Cross Slope (%)	Slope Direction (in / out)	Comments:
1	11.415	R1	O	1.3	2.9					0.5		0.3		0.9	5.9	STAB	2.0	B	II	M	P				
2	11.527	R1	O	1.1	3.3										4.4	CONC=8.8	1.9	B	II	M	P				spalling, widening
3	11.700	R1	N	1.2	3.5					0.5		1.4			6.6	CONC	6.6	B	II	M	P				
4	12.000	R1	N	1.3	3.5					0.5				0.6	5.9	CONC	3.5	B	II	M	P				
5	12.400	R1	N	1.2	3.4					0.5				0.6	5.7	CONC	5.1	B	II	M	P				
6	12.655	R1	O	1.0	4.5					0.5		4.5			10.5	CONC					P				
7	13.000	R1	O	1.2	3.5					0.5		1.0		0.9	7.1	LR=10.3	7.1	B	II	M	P				shoving
8	13.267	R1	N	0.9		0.9			3.4		0.8				12.4	ABC=7.0	2.7	B	IB	M	P				
9	12.779	RAgR	I	0.8			0.6					1.9			3.3	LR					F				curve
10	12.864	RAgR	N	1.2	1.0			1.0	2.7			0.9			6.8	LR	5.2	B	II	M	P				
11	11.500	L1	I	1.1	4.1										5.2	CONC					P				
12	11.835	L1	N	0.9	3.9							0.9			5.7	CONC					F				
13	12.100	L1	I	0.8	2.0							2.4			5.2	CONC	1.1	B	II	M	P				
14	12.500	L1	N	0.9	3.5							1.4			5.8	LR	5.8	B	II	M	P				
15	12.800	L1	N	0.9	3.7					0.5		5.3			10.4	CONC					F				curve
16	13.100	L1	N	1.6	3.0							0.7			5.3	CONC					P				
17	13.268	L1	N	1.3				3.1					7.1		11.5	CONC=7.1	11.5	B	II	M	P				shoving, grinding
18	11.700	OR	N	1.6	3.0										4.6	STAB					F				
19	12.655	OR	N	1.0	5.4										6.4	STAB					F				
20	13.267	OR	N	1.4											1.4	RAP=5.0					F				

Remarks: RAgR = Right Side Ag Inspection Ramp

Pavement Evaluation Coring and Condition Data

Cored By:	UNIVERSAL	Date:	07/21/21	Page 2 of 4	Typical Section 2 of 3
Project No.:	210673-3-52-01	Name:	SR5(US17) From Lippizan Court To GA State Line		

Core Number	Mile Post	Lane	Wheel Path	Pavement Layer (top) FC95	SP125	T1	T2	ST		Core Length	Base Type	Crack Depth	Crack Type	Crack Class	Crack Extent	Pavement Condition	Rut Depth (inches)	Cross Slope (%)	Slope Direction (in / out)	Comments:
21	11.500	OL	N	1.3	4.5			0.5		6.5	LR=6.3					F				
22	12.100	OL	N	0.8	4.2	1.5				6.5	LR					F				
23	13.100	OL	N	1.0	1.0	1.5	2.1	0.3		6.9	LR=4.8					F				

Remarks:

EXTRA INFORMATIONAL CORES

Cored By:	UNIVERSAL	Date:	07/21/21	Page 4 of 4	Typical Section 2 of 3
Project No.:	210673-3-52-01	Name:	SR5(US17) From Lippizan Court To GA State Line		

Core Number	Mile Post	Lane	Wheel Path	Pavement Layer (top) FC95	SP125	T1	T2	ST		Core Length	Base Type	Crack Depth	Crack Type	Crack Class	Crack Extent	Pavement Condition	Rut Depth (inches)	Cross Slope (%)	Slope Direction (in / out)	Comments:
A	12.820	LAgR	N	0.3	2.5	0.7	0.8			4.3	LR					P				

Remarks: LAgR = Left Side Ag Inspection Ramp