Pavement Evaluation Coring and Condition Data

Cored By:	UNIVERSAL	Date:	05/23/18	Page 1 of 1	Typical Section: 1 of 1
Project No.:	437374-1-52-01	Name:	SRA1A		Lanes: 2
State Road No.:	A1A	From:	at Mary St		Shoulders
County:	St. Johns	To:			Inside: -
Section No:	78040000	Beg MP: 8.650	End MP: 8.670	Length: 0.020	Outside: Paved 5'

Core Number	Mile Post	Lane	Wheel Path	Pavement Layer (top) FC125	SP125	ARMI	T1	T2	ST	Core Length	Base Type	Crack Depth	Crack Type	Crack Class	Crack Extent	Pavement Condition	Rut Depth (inches)	Cross Slope (ft per 6 ft.)	Slope Direction (in / out)	Comments:
1	8.650	R1	Y	1.4	1.5	0.5		0.3	0.4	4.1	LR	1.4	B	IB	L	P				SR / Separation at 1.4"
2	8.718	R1	N	1.5	1.4	0.5		0.2	0.5	4.1	LR = 7.6					P				SR
3	8.786	R1	Y	1.4	1.1	0.5			0.7	3.7	LR	2.3	B	IB	L	P				SR
4	8.659	L1	Y	1.1	1.5				0.6	3.2	LR	3.2	B	IB	L	P				SR / no ARMI
5	8.737	L1	Y	1.6	1.5	0.7				3.8	LR = 7.6					P				SR
6	8.801	L1	Y	1.3	1.4	0.5		0.2	0.5	3.9	LR	2.7	B	IB	L	P				SR
7	8.645	OR	N	1.5	1.7		2.2			5.4	LR					F				
8	8.786	OR	N	1.4	2.0		2.5			5.9	STAB					F				
9	8.659	OL	N	1.7	1.6		2.0			5.3	STAB					F				
10	8.801	OL	N	1.4	1.8		2.2			5.4	STAB					F				
A	8.686	TO	N				2.5	4.0		6.5	SHEL					P				SR

Remarks: