

Pavement Evaluation Coring and Condition Data

Cored By: District 2 Materials				Date: 01/14/25		Page 1 of 1				Mainline			
Project No.: 438610-1-52-01				Name: I-95(SR 9) St Johns NB Rest Area				Lanes: NA					
State Road No.: SR 9				From: I-95 NB Off Ramp				Shoulders					
County: St Johns				To: I-95 NB On Ramp				Inside: NA					
Section No: 78080005				Beg MP: 0.000		End MP: 0.376		Length: 0.376		Outside: NA			

Core Number	Location	Lane	Wheel Path	Pavement Layer							Core Length (in)	Base Type	Crack				Payt. Condition	Rut Depth (in.)	Cross Slope %	Slope Direction (I=in / O=out)	Comments:
				FC 12.5	FC 5	T-S	SP 12.5	T-S						Depth (in.)	Type	Class					
1	S e e A t t a c h m e n t	OR	N	1.5		5.5					7.0	ABC=8.8"					G				
2		DCEL	O		0.6		2.8				3.4	LR					G				
3		TPK	N	1.5			1.4	1.7			4.6	LR=10.4"					F				
4		TPK	N	1.5			2.8				4.3	LR					F				SLIGHT RAVELING
5		TPK	N	1.5			2.0				3.5	LR					P				MODERATE RAVELING, SPALLING
6		PIC	N	1.6		0.8					2.4	ABC=7.0"	2.3	B	II	M	F				SLIGHT RAVELING
7		PIC	N	1.4		1.0					2.4	ABC=6.2"					G				
8		DRIVE	O	1.5			1.6				3.1	LR					F				MODERATE RAVELING, SPALLING
9		CPK	N	1.4			1.0	1.9			4.3	LR					F				SLIGHT RAVELING
10		CPK	O	1.8				1.5			3.3	LR=11.9"					F				SLIGHT RAVELING
11		TPK	N	1.4			1.3				2.7	LR					F				
12		TPK	O	1.5			1.8				3.3	LR					P				SLIGHT RAVELING
13		TPK	I	1.6			1.6	1.1			4.3	LR=10.2"	2.4	B	II	M	P				MODERATE RAVELING
14		Ramp	O	1.4			1.3				2.7	LR	2.7	B	II	S	P				SEVERE RAVELING, SPALLING
15		OR	O	1.5							1.5	LR					P				SEVERE RAVELING

Remarks: TPK= TRUCK PARKING CPK=CAR PARKING PIC= PICNIC AREA