

## Pavement Evaluation Coring and Condition Data

Cored By: CSI GEO, Inc				Date: 02/06/25		Page 1 of 3				Mainline			
Project No.: 432313-2-52-01				Name: SR 312				Lanes: 4					
State Road No.: SR 312				From: SR 207				Shoulders					
County: St Johns				To: West of SR 5				Inside: 2' PAVED					
Section No: 78002900				Beg MP: 0.000		End MP: 0.935		Length: 0.935		Outside: 4' PAVED			

  

Core Number	Mile Post	Lane	Wheel Path	<div style="display: flex; align-items: center;"> <span style="margin-right: 5px;">←</span> <div style="border: 1px solid black; padding: 2px 5px;">Top</div> <span style="margin-left: 5px;">Pavement Layer</span> </div>								Core Length (in.)	Base Type	Crack				Pavement Condition	Rut Depth (in.)	Cross Slope (%)	Slope Direction (in / out)	Comments:
				FC 9.5	SP 12.5	S-1								Depth (in.)	Type	Class	Extent					
1	0.100	R1	Y	1.5	2.0						3.5	LR	3.5	B	II	L	P					
2	0.389	R1	Y	0.9	0.9	0.7					2.5	LR	2.5	B	II	L	P				Grinding	
4	0.500	R1	Y	1.0	1.4	1.1					3.5	LR					F					
5	0.800	R1	N	1.3	2.3						3.6	LR=8"					F					
6	0.010	R2	Y	1.2	1.2						2.4	LR	2.4	B	II	L	P				Raveling	
7	0.276	R2	Y	1.1	2.1						3.2	LR=8"	3.2	B	II	M	P				Raveling	
9	0.397	R2	Y	1.4	1.6						3.0	LR					P					
10	0.600	R2	Y	1.0	2.2						3.2	LR	3.2	B	III	M	P				Grinding and Spalling	
11	0.900	R2	N	1.1	1.8	0.8					3.7	LR	3.7	B	II	M	P				Grinding and Spalling	
12	0.010	L1	Y	1.1	1.7						2.8	LR=9"	2.8	B	III	M	P					
13	0.359	L1	N	1.3	1.4	1.7					4.4	LR					F					
15	0.600	L1	N	1.0	1.5	1.7					4.2	LR	2.4	B	II	L	P					
16	0.900	L1	N	0.5	2.4	1.0					3.9	LR					F					
17	0.042	L2	N	1.5	1.5						3.0	LR	3.0	B	II	L	P					
19	0.397	L2	N	1.4	1.0	0.7					3.1	LR	0.5	B	II	L	P				Grinding, Raveling	
20	0.500	L2	Y	1.2	1.2	2.2					4.6	LR	4.6	B	II	L	P				Grinding, Raveling	

  

Remarks: \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Pavement Evaluation Coring and Condition Data

Cored By: CSI GEO, Inc				Date: 02/06/25				Page 2 of 3				Mainline										
Project No.: 432313-2-52-01				Name: SR 312				Lanes: 4														
State Road No.: SR 312				From: SR 207				Shoulders														
County: St Johns				To: West of SR 5				Inside: 2' PAVED														
Section No: 78002900				Beg MP: 0.000		End MP: 0.935		Length: 0.935		Outside: 4' PAVED												
Core Number	Mile Post	Lane	Wheel Path	<div>← Top Pavement Layer</div>							Core Length (in.)	Base Type	Crack				Pavement Condition	Rut Depth (in.)	Cross Slope (%)	Slope Direction (in / out)	Comments:	
				FC 9.5	SP 12.5	S-1								Depth (in.)	Type	Class						Extent
21	0.800	L2	N	1.2	1.3	0.7						3.2	LR=10"				F					
22	0.100	OR	N	1.1	2.0							3.1	LR				F					
23	0.600	OR	N	1.7	2.0							3.7	LR=11"				F					
24	0.042	OL	N	1.6	1.7							3.3	LR=7"				F					
25	0.500	OL	N	1.9	2.6							4.5	LR				F					
26	0.765	RRTTL	N	1.1	2.4							3.5	LR				P					Raveling
27	0.079	LRTTL	N	2.0	1.4							3.4	LR				F					
28	0.180	LLTTL	N	0.9	1.5	0.5						2.9	LR				F					
29	0.715	LLTTLL	N	1.1	1.9							3.0	LR	3.0	B	II	L	P				
30	0.859	LRTTL	N		2.6							2.6	LR				F					
31	0.151	RTO	N		2.1							2.1	LR				F					News
32	0.801	LTO	N	1.1	2.4							3.5	LR				F					Moultrie Rd
33	0.079	IR	N	1.5	2.6							4.1	LR				F					
34	0.600	IL	N		2.4							2.4	LR				F					

Remarks: \_\_\_\_\_

\_\_\_\_\_

## Bridge Approach / Leave Slab / Deck

Cored By:	CSI GEO, Inc	Date:	02/06/25	Page	3	of	3	Mainline	
Project No.:	432313-2-52-01	Name:	SR 312					Lanes:	4
State Road No.:	SR 312	From:	SR207					Shoulders	
County:	St Johns	To:	WEST OF SR5					Inside:	2' PAVED
Section No:	78002900	Beg MP:	0.000	End MP:	0.935	Length:	0.935	Outside:	4' PAVED

[illegible]

Remarks:	