

**State of Florida Department of Transportation
PAVEMENT EVALUATION AND CONDITION DATA SHEET**

Project No.: 436127-1	Cored By: FDOT (JJ,RS)	Date: 4/6/2017	Page No.: 1 of 1
County: Lake	Highway Sect. No.: 11020	From: 639' South of CR 561	To: 1024' North of CR 561
Road No.: SR 33	Begin M.P.: 3.291	End M.P.: 3.606	Length: 0.315

Core No.	MP	Distance from left edge of lane (ft)	Lane	Wheel Path	Pavement Layer (in.)							Base		Crack				Pavt Cond.	Rut Depth (in)	Cross Slope (%)	Comments				
					FC 12.5	Type SP	Type S	Type III	Surface Treatment		Core Length (in)	Type	Thick-ness (in)	Depth (in)	Type	Class	Extent								
1	3.350	9.5	R1	X	1.4	1.2		0.3	0.4			3.3	LR	6.8	1.4	BR	I	L	F						
2	3.350	2.0	OR		1.8		2.0					6.8	ABC	3.0	--	--	--	--	F						
3A	3.406		Apron		2.0							2.0	LR	8.6	B	SL	II	M	F				Cored on a pavement joint at Right of Way of SR 33 and CR 561		
3B	3.406		Apron			1.5						1.5	LR	9.1	B	SL	II	M	F				Cored on a pavement joint at Right of Way of SR 33 and CR 561		
4	3.482	9.5	L1	X	1.5	1.3		0.3	0.3			3.4	LR	6.9	--	--	--	--	F						
5	3.482	2.0	OL		1.3		1.8					7.2	ABC	4.1	--	--	--	--	F				Drop off conditions exist		

Remarks: A=Alligator B=Base BL=Block BR=Branch Cracking OGFC= Open-Graded FC Stress Cracks SL=Single Longitudinal Crack L=Light Cracking
M=Moderate Cracking S=Severe Cracking G=Good F=Fair P=Poor ST=Single Transverse Crack LR=Limerock LML=Westbound Merge Lane
ABC = Asphalt Base Course SC= Soil Cement RRTL=North or Eastbound Right Turn Lane RLTL=North or Eastbound Left Turn Lane
SE = Super-elevated LRTL= South or Westbound Right Turn Lane LLTL=South or Westbound Left Turn Lane NB=No Base