State of Florida Department of Transportation PAVEMENT EVALUATION AND CONDITION DATA SHEET Project No.: 413590-1 Cored By: PSI - Professional Service Industries **Date:** 9/2/2020 (revised) 6/16/2003 (cored) **Page No.:** 1 of 2 N.. Of Apopka Vineland Road County: Orange Highway Sect. No: 75050 From: To: SR 500 / US 441 / Orange Blossom Trail Road No.: SR 50 Begin MP: 10.317 End MP: 15.977 Length: 5.660 miles Base Crack istance fro Core Wheel Rut Depth left edge of Lane Pavt Cond Path Thick-ness ore Length FC-9.5 FC-4 Type S Type I Type II Binder Class Extent 141 12.883 LLTL 1.0 1.1 1.2 1.7 5.0 L/R To Pine Hills Rd 6.0 11.0 166 12.984 6.0 RLTL 1.0 0.8 11.0 ABC 8.2 To Car Lot 140 13.016 1.0 10.5 LLTL X 2.5 11.2 ABC 8.7 To Tire Store 139 13.182 2.5 LLTL 1.0 0.5 1.3 1.6 L/R 11.8 To Delphi St. 167 13.207 3.0 RLTL 1.0 0.8 1.8 L/R 9.8 To Barnett Park 138 13.300 LLTL 1.0 L/R 10.2 1.0 To Montgomery St 13.350 8.0 RLTL 1.0 4.0 11.2 168 3.0 L/R To Silverton St 137 13.370 2.0 LLTL 1.0 0.7 1.8 1.4 4.9 L/R 9.8 To Silverton St 13.534 1.0 136 MXO 1.1 1.7 1.3 5.1 L/R 10.7 135 13.647 MXO 1.0 1.3 1.4 1.4 5.1 L/R 10.2 169 13.717 6.0 RLTL 1.0 1.0 1.1 1.2 4.8 L/R 11.0 To Fairvilla Rd 134 13,786 6.0 LLTL 1.0 0.4 1.5 1.5 4.4 10.7 To Fairvilla Rd L/R 170 13.830 RLTL 1.0 1.9 2.9 L/R 10.7 To Mercy Dr 133 13.903 LLTL X 1.0 0.7 1.5 1.8 5.0 L/R 9.9 To Mercy Drive 132 14.034 4.0 LLTL 1.0 1.7 2.7 L/R 9.0 To Jaguar Dealer 131 14.144 1.0 10.5 MXO 0.5 L/R

Remarks: Crack Depth of "B" indicates full depth crack to the base. EOP = Edge of Pavement

Crack Extent: L= Light; M= Moderate; S= Severe Pavement Condition: G= Good; F= Fair; P= Poor

Crack Types: A= Alligator; Bl= Block; Br= Branch; SL= Single Longitudinal; ST= Single Transverse; R= Reflective; J= Joint; OGFC= Open-Graded FC Stress Crack

Base Types: LR= Limerock; COQ= Coquina; SC= Soil Cement; ABC= Asphalt Base; SAHM= Sand Asphalt Hot Mix; SBRM= Sand Bituminous Road Mix; NB= No Base

State of Florida Department of Transportation PAVEMENT EVALUATION AND CONDITION DATA SHEET Project No.: 413590-1 Cored By: PSI - Professional Service Industries **Date:** 9/2/2020 (revised) 6/16/2003 (cored) **Page No.:** 2 of 2 County: Orange Highway Sect. No: 75050 From: N.. Of Apopka Vineland Road To: SR 500 / US 441 / Orange Blossom Trail SR 50 Begin MP: 10.317 End MP: 15.977 Road No.: Length: 5.660 miles Crack Base Core from left Wheel Rut Depth Cross Slop Lane Pavt Cond Comments edge of lane Path Core Length Thick-ness FC-9.5 FC-4 Type S Type I Type II Binder Class Extent 130 14.261 MXO 1.0 0.8 1.0 1.5 4.3 L/R 9.9 Worn 171 14.466 3.0 RLTL X 1.0 0.9 1.4 1.6 4.9 L/R 11.3 To Ferguson St 0.8 129 14.515 6.0 LLTL 1.6 2.0 5.4 L/R 11.1 To Ferguson Dr 128 14.583 MXO 1.6 1.8 5.3 L/R 10.2 127 14.721 MXO 0.1 2.1 5.1 L/R 10.7 No bond between T-S and T-I 1.8 2.2 5.4 11.7 172 14.808 RLTL 1.0 L/R To SR 423 X 0.4 3.0 4.4 L/R 11.4 173 14.848 3.0 RLTL 1.0 To SR 423 125 14.948 11.0 L-LLTL X 1.0 3.4 10.9 ABC 6.5 To SR 423 X 126 14.948 3.0 R-LLTL 1.0 3.5 10.4 ABC 5.9 To SR 423 174 15.028 9.0 RLTL X 1.0 1.9 11.3 ABC 8.4 To Pawn Shop 15.071 3.5 LLTL X 1.0 3.7 11.8 ABC 7.1 To Sheriff's Office 124 175 15.102 4.5 RLTL 1.0 1.9 11.5 ABC 8.6 To Texas Ave 123 15.244 6.0 LLTL 1.0 1.1 5.4 L/R 10.3 To Tag Agency 176 15.343 7.5 RLTL X 1.0 1.0 3.4 L/R 11.6 To County Lane

Remarks: Crack Depth of "B" indicates full depth crack to the base. EOP = Edge of Pavement

Crack Extent: L= Light; M= Moderate; S= Severe Pavement Condition: G= Good; F= Fair; P= Poor

Crack Types: A= Alligator; Bl= Block; Br= Branch; SL= Single Longitudinal; ST= Single Transverse; R= Reflective; J= Joint; OGFC= Open-Graded FC Stress Crack

Base Types: LR= Limerock; COQ= Coquina; SC= Soil Cement; ABC= Asphalt Base; SAHM= Sand Asphalt Hot Mix; SBRM= Sand Bituminous Road Mix; NB= No Base