

**State of Florida Department of Transportation
PAVEMENT EVALUATION AND CONDITION DATA SHEET**

Project No.: 437133-1	Cored By: FDOT(JJ)	Date: 8/31/2016	Page No.: 1 of 1
County: Volusia	Highway Sect. No: 79040-000	From: Mandarin Ave	To: Kentucky Ave
Road No.: SR 15/600 (US 17-92)	Begin M.P.: 14.752	End M.P.: 14.854	Length: 0.102

Core No.	MP	Distance from left edge of lane (ft)	Lane	Wheel Path	Pavement Layer (in.)					Base		Crack				Pavt Cond.	Rut Depth (in)	Cross Slope (%)	Comments
					FC 12.5	Type S	Surface Treatment	Binder	Core Length (in)	Type	Thick-ness (in)	Depth (in)	Type	Class	Extent				
1	14.854	7.5	R2		1.1	1.3			2.4	LR	8.2	--	--	--	--	G			
2	14.854	6.0	LLTL		1.5			1.1	2.6	LR	8.0	--	--	--	--	G			
3	14.768	6.0	L2		1.2	1.5			2.7	LR	9.2	--	--	--	--	G			
4	Side Street	6.0	L1			2.1	0.3		2.4	NB	--	--	--	--	--	P		Westbound lane Mandarin Ave. 95' west of outside edge of SR 15/600	
5	Side Street	6.0	R1			2.5	0.3		2.8	NB	--	--	--	--	--	P		Eastbound lane Mandarin Ave. 350' west of outside edge of SR 15/600	

Remarks: A=Alligator B=Base BL=Block BR=Branch Cracking OGFC= Open-Graded FC Stress Cracks SL=Single Longitudinal Crack L=Light Cracking
M=Moderate Cracking S=Severe Cracking G=Good F=Fair P=Poor ST=Single Transverse Crack LR=Limerock LML=Westbound Merge Lane
ABC = Asphalt Base Course SC= Soil Cement RRTL=North or Eastbound Right Turn Lane RLTL=North or Eastbound Left Turn Lane
SE = Super-elevated LRTL= South or Westbound Right Turn Lane LLTL=South or Westbound Left Turn Lane NB=No Base