

STATE OF FLORIDA DEPARTMENT OF TRANSPORTATION
PAVEMENT EVALUATION CORING AND CONDITION DATA

Cored by: Shannon Davidson / Andre Mondor Date: 10/29/18 through 11/01/18 Page of Typical Section No.: ---

W.P.I. No.:				Name:				Lanes: Varies					
Fin. Proj. ID: 441650-1-52-01				From: West of US 19/ SR 55				Shoulder Type and Condition: Paved					
F.A. Proj. No.:				To: E of the Shoppes Entrance				Inside:					
County: Pinellas		SR No.: 694		Beg MP: 0		End MP: 0.177		Lgth: 0.177		Outside:			
Median Curbed (Y / N):				Lawn				Other:				Curb & Gutter (Y / N): N	

Core No.	Mile Post or Sta. No.	Lane	W P h e e l	Pavement Layer (in.)								Base		Crack				P C o n d	D R e p t h (in.)	C S r l o o s p s e (%)	Comments
				SP12	SP2C	S1	S2	S1	S2	Bind	Core Lgth (in.)	Limerock	D e p t h (in.)	T y p e	C l a s s	E x t e n t					
PC-01	-	WB	Y	1.6	-	0.9	1.3	-	-	-	3.8	10.0	-	-	-	-	-	Poor		WB Frontage Road - FL West Coordinates: E 434631 W 1274978	
PC-02	-	WB	N	2.0	8.3	-	-	-	-	-	10.3	-	-	0.9	-	IB	Light	Fair		0.9" Hairline crack - Could not Perform on Lane without blocking traffic - WB Frontage Road - FL West Coordinates: E 433955 W 1274946	
PC-03	0.08	R2	Y	1.0	0.5	-	2.4	-	-	-	3.9	10.0	-	2.0	B	III	Mod	Poor		Longitudinal Branch Crack	
PC-04	0.14	R2	Y	1.8	-	-	3.4	-	-	1.4	6.5	8.5	-	1.9	-	III	Mod	Poor		Aligator crack - Layers separating @ 4.5"	
PC-05	0.19	R1	Y	2.0	-	-	0.9	2.1	-	-	5.0	12.0	-	2.5	-	III	Mod	Poor		Aligator crack	
PC-06	0.15	RLT	N	1.3	-	2.6	-	-	-	-	3.9	12.0	-	1.5	-	IB	Light	Fair		1.5" Hairline Crack	
PC-07	0.12	IR	-	1.6	-	-	0.5	2.4	-	-	4.5	7.5	-	-	-	-	-	Fair		-	
PC-08	0.10	IL	-	2.1	-	-	-	-	-	-	2.1	8.0	-	-	-	-	-	Good		-	
PC-09	0.05	L1	-	1.5	-	-	2.6	-	-	-	4.1	13.0	-	2.4	-	IB	Light	Fair		2.4" hairline crack - Surface polishing	
PC-10	0.03	L2	-	1.8	-	-	1.5	0.6	0.6	1.1	5.6	10.0	-	2.3	-	II	Mod	Poor		2.3" crack - SP layer aggregate loss	
PC-11	0.04	L2	-	1.1	-	2.0	-	-	-	-	3.1	12.0	-	2.3	-	IB	Light	Fair		2.3" hairline crack	
PC-12	-	OL	-	1.3	-	1.0	-	-	-	-	2.3	14.0	-	1.3	-	IB	Light	Good		1.3" Hairline crack	
PC-13	-	EB	Y	1.3	1.0	2.8	-	-	-	-	5.0	10.0	-	1.5	-	IB	Light	Fair		Aligator Cracks - EB Frontage Road - FL West Coordinates: E 434643 W 1274810	