

PAVEMENT EVALUATION CORING AND CONDITION DATA

Cored by:	C. Malone, P. Griffith				Dates Cored:	6/30/19 - 7/3/19			Page:	1	of	15	Typical Section No.:	1															
W.P.I. No.:								Name: 55					Lanes: 6																
Fin. Proj. ID: 440246-1								From: SR 682 / 54th Ave S					Shoulder Type and Condition: Curb																
F.A. Proj. No.:								To: 22nd Ave N					Inside:																
County: Pinellas								Beg MP: 0.867	End MP: 5.878	Lgth: 5.011	Outside:																		
Median Curbed (Y / N): N				Paved	Lawn	Other:	Vegetation								Curb & Gutter (Y / N): Y														
Core No.	Mile Post or Sta. No.	Lane	Wheel Path	Pavement Layer (in.)										Base			Subgrade	Crack			Pvmt Cond	Rept	CS	Riloo spsse	Comments				
				F125	F95	FC5	SP 125	SP 9.5	SP2F	T1	S	S2	BIND	SBRM	RAP	Core Lgth (in.)	Lime rock	Shell	A B C	Concrete						stabili zed	Depth (in.)	Type	Class
1	0.902	L3	Y	0.5	--	--	2.3	--	--	--	1.1	--	1.0	--	--	4.9	11.0	--	--	--	2.5	B	II	M	Fair		Right Turn Lane		
2	1.020	L1	Y	1.7	--	--	2.1	--	--	--	--	--	--	--	--	3.8	0.0	--	8.2	--	--	--	--	--	--	Fair		Left Turn Lane	
3A	1.160	R1	N	--	--	1.1	--	--	--	--	1.3	--	--	--	--	2.4	9.5	--	--	--	2.4	B	II	L	Poor		Left Turn Lane		
3B	1.160	R1	N	1.3	--	--	--	--	--	--	1.4	--	--	--	--	2.7	14.0	--	--	--	--	--	--	--	--	Fair			
4	1.239	R3	Y	1.7	--	--	--	--	--	--	1.1	--	1.3	--	--	4.1	14.0	--	--	--	2.0	A	IB	M	Fair				
5	1.238	R2	Y	1.5	--	--	--	--	--	--	0.8	0.7	1.7	--	--	4.7	12.0	--	--	--	1.4	B	II	M	Fair				
6	1.238	R1	Y	1.2	--	--	--	--	--	--	0.8	1.2	2.1	--	--	5.3	9.0	--	--	--	7.0	5.3	B	II	M	Poor			
7	1.237	L2	Y	--	1.6	--	--	--	--	--	1.2	0.4	2.0	--	--	5.2	14.5	--	--	--	2.3	A	IB	M	Fair				
8	1.238	L1	Y	1.4	--	--	--	--	--	--	1.0	0.8	2.1	--	--	5.3	13.5	--	--	--	--	--	--	--	--	Fair			
9	1.237	L3	Y	1.7	--	--	--	--	--	--	0.8	--	1.8	--	--	4.3	15.0	--	--	--	2.7	A	II	M	Poor				
10	1.356	R1	Y	1.5	--	--	--	--	--	--	0.9	1.5	2.6	--	--	6.5	11.0	--	--	--	1.6	A	IB	L	Fair		Left Turn Lane		
11	1.464	R1	Y	1.7	--	--	--	--	--	--	4.7	--	--	--	--	6.4	16.0	--	--	--	2.5	B	II	M	Fair		Left Turn Lane		
12	1.535	L3	N	1.3	--	--	--	--	--	--	2.4	--	--	--	--	3.7	16.0	--	--	--	--	--	--	--	--	Fair		Right Turn Lane	
13	1.638	R3	Y	1.5	--	--	--	--	--	--	1.3	1.6	--	--	--	4.4	13.5	--	--	--	--	1.9	A	II	M	Fair			
14	1.638	R2	Y	1.4	--	--	--	--	--	--	1.0	--	1.7	--	--	4.1	12.5	--	--	--	2.8	A	II	L	Fair				
15	1.638	R1	Y	1.3	--	--	--	--	--	--	0.9	1.0	2.0	--	--	5.2	16.5	--	--	--	9.0	5.2	B	II	L	Poor			
16	1.638	L1	Y	1.4	--	--	--	--	--	--	1.0	0.8	2.1	--	--	5.3	16.0	--	--	--	2.8	B	IB	L	Fair				
17	1.638	L2	Y	1.4	--	--	--	--	--	--	0.6	0.8	2.5	--	--	5.3	12.0	--	--	--	5.3	A	II	M	Poor				
18	1.638	L3	Y	1.2	--	--	--	--	--	--	0.9	--	1.6	--	--	3.7	12.0	--	--	--	2.5	A	II	L	Fair				
19	1.678	R3	Y	1.0	--	--	--	--	--	--	2.5	--	--	--	--	3.5	16.0	--	--	--	--	--	--	--	--	Fair		Right Turn Lane	
20	1.745	L3	Y	1.6	--	--	--	--	--	--	0.8	--	--	--	--	2.4	16.0	--	--	--	2.4	B	III	L	Poor		Right Turn Lane		
21	1.817	L1	Y	1.8	--	--	--	--	--	--	0.7	1.0	2.0	--	--	5.5	17.0	--	--	--	--	--	--	--	--	Fair		Left Turn Lane	
22	1.956	R1	Y	1.8	--	--	--	--	--	--	4.0	--	--	--	--	5.8	0.0	--	5.8	--	--	--	--	--	--	--	Fair		Left Turn Lane
23	2.048	R3	Y	1.1	--	--	--	--	--	--	5.0	--	1.7	--	--	7.8	12.8	--	--	--	2.2	A	II	S	Poor				
24	2.046	R2	Y	--	1.3	--	--	--	--	--	1.5	0.5	1.7	--	--	5.0	14.0	--	--	--	2.7	B	II	M	Fair				
25	2.047	R1	Y	1.5	--	--	--	--	--	--	0.7	0.8	1.9	--	--	4.9	13.5	--	--	--	8.0	4.9	B	II	M	Poor			
26	2.047	L1	Y	1.3	--	--	--	--	--	--	0.5	1.1	2.2	--	--	5.1	16.0	--	--	--	8.0	5.1	B	III	L	Poor			
27	2.047	L2	Y	1.8	--	--	--	--	--	--	1.0	0.9	1.8	--	--	5.5	10.0	--	--	--	4.8	B	II	M	Fair				
28	2.045	L3	Y	1.5	--	--	--	--	--	--	3.5	--	1.8	--	--	6.8	13.0	--	--	--	2.3	B	II	L	Fair				
29	2.098	R1	Y	--	0.5	--	--	--	--	--	1.9	--	--	--	--	2.4	15.0	--	--	--	2.4	B	III	M	Poor		Left Turn Lane; Wires from abandoned signal loop apparent		
30	2.172	L3	Y	1.2	--	--	--	--	--	--	3.8	--	--	--	--	5.0	0.0	--	9.0	--	--	--	--	--	--	--	Fair		Right Turn Lane
31	2.312	L1	Y	--	0.7	--	--	--	--	--	4.9	--	--	--	--	5.6	15.5	--	--	--	--	--	--	--	--	Fair		Left Turn Lane	
32	2.471	L3	Y	1.7	--	--	--	--	--	--	--	--	--	--	--	1.8	3.5	0.0	--	--	--	--	--	--	--	Fair		Right Turn Lane	
33	2.566	R3	Y	0.9	--	--	--	--	--	--	0.6	0.9	2.2	--	--	4.6	13.0	--	--	--	4.6	B	III	M	Poor				
34	2.565	R2	Y	1.2	--	--	--	--	--	--	0.9	0.8	2.2	--	--	5.1	10.0	--	--	--	6.0	5.1	C	III	S	Poor			

PAVEMENT EVALUATION CORING AND CONDITION DATA

Cored by:	C. Malone, P. Griffith				Dates Cored:	6/30/19 - 7/3/19		Page:	2	of	15	Typical Section No.:	1														
W.P.I. No.:	Name: 55						Lanes: 6																				
Fin. Proj. ID:	From: SR 682 / 54th Ave S						Shoulder Type and Condition: Curb																				
F.A. Proj. No.:	To: 22nd Ave N						Inside:																				
County:	Beg MP: 0.867 End MP: 5.878 Lgth: 5.011						Outside:																				
Median Curbed (Y / N):	N	Paved	Lawn	Other:	Vegetation						Curb & Gutter (Y / N): Y																
Core No.	Mile Post or Sta. No.	Lane	Wheel Path	Pavement Layer (in.)								Base		Subgrade	Crack		Pvmt Cond	Rept (in.)	CSR I (spss)	Comments							
				F125	F95	FC5	SP 125	SP 9.5	SP2F	T1	S	S2	BIND	SBRM	RAP	Core Lgth (in.)					Limerock	Shell	A B C	Concretized	stab (in.)	Depth Type	Class
35	2.565	R1	Y	1.5	--	--	--	--	--	1.2	1.2	1.8	--	--	5.7	16.0	--	--	--	5.7	B	III	M	Poor			
36	2.564	L1	Y	1.3	--	--	--	--	--	6.7	--	--	--	--	8.0	0.0	--	8.5	--	--	3.3	B	II	M	Fair		
37	2.564	L2	Y	1.2	--	--	--	--	--	4.5	--	--	--	--	5.7	0.0	--	10.3	--	--	--	--	--	--	Fair		
38	2.564	L3	N	--	1.5	--	--	--	--	3.0	--	--	--	--	4.5	0.0	--	10.0	--	--	2.0	B	1B	L	Fair		
39	2.661	L1	Y	1.4	--	--	3.5	--	--	--	--	--	--	--	4.9	0.0	--	5.4	--	--	--	--	--	--	Fair		
40	2.794	R1	Y	1.2	--	--	--	--	--	1.5	--	1.7	2.3	--	6.7	16.0	--	--	--	--	--	--	--	--	Fair		
41	2.947	R1	Y	1.4	--	--	--	--	--	--	--	1.0	1.7	--	4.1	13.0	--	--	--	--	--	--	--	--	Fair		
42	2.983	R3	Y	--	1.1	--	--	1.0	--	--	--	1.5	--	--	3.6	7.5	--	--	--	--	--	--	--	--	Fair		
43	2.983	R2	Y	1.5	--	--	--	--	--	--	1.2	--	1.2	--	3.9	9.5	--	--	--	6.0	2.3	A	II	S	Poor		
44	2.983	R1	Y	1.4	--	--	--	--	--	--	1.3	--	1.7	--	4.4	9.0	--	--	--	--	2.5	A	II	S	Poor		
45	2.983	L1	N	1.3	--	--	--	--	--	--	2.0	--	1.3	--	4.6	10.0	--	--	--	--	3.0	B	II	M	Poor		
46	2.983	L1	Y	1.3	--	--	--	--	--	--	1.3	--	1.3	--	3.9	7.0	--	--	--	3.0	2.2	B	II	L	Fair		
47	2.983	L2	Y	1.5	--	--	--	--	--	--	0.6	--	1.7	--	3.8	8.5	--	--	--	--	1.7	B	IB	L	Fair		
48	2.983	L3	Y	1.3	--	--	--	--	--	--	1.2	--	1.5	--	4.0	8.5	--	--	--	--	3.0	B	II	L	Fair		
49	3.158	L1	Y	1.2	--	--	--	--	--	--	1.6	--	1.2	--	4.0	15.0	--	--	--	--	4.0	B	II	L	Poor		
50	3.274	L1	Y	1.6	--	--	--	--	--	0.6	--	0.7	1.5	--	4.4	13.0	--	--	--	--	--	--	--	--	Fair		
51	3.394	L1	Y	1.4	--	--	--	--	--	0.6	0.9	--	1.5	--	4.4	9.5	--	--	--	--	2.1	A	II	L	Fair		
52	3.518	L1	Y	1.4	--	--	--	--	--	2.2	0.7	--	--	--	4.3	0.0	--	12.8	--	--	--	--	--	--	--	Fair	
53	3.642	L1	Y	1.6	--	--	--	--	--	1.4	--	--	1.8	--	4.8	15.8	--	--	--	--	2.9	C	II	M	Fair		
54	3.706	R3	Y	1.5	--	--	--	--	--	--	1.1	--	1.2	--	3.8	11.0	--	--	--	--	--	--	--	--	Fair		
55	3.706	R2	Y	1.5	--	--	--	--	--	--	0.8	--	1.8	--	4.1	9.0	--	--	--	--	--	--	--	--	Fair		
56	3.706	R1	Y	1.6	--	--	--	--	--	--	1.0	--	1.4	--	4.0	9.0	--	--	--	--	1.5	A	II	M	Fair		
57	3.706	L1	Y	1.3	--	--	--	--	--	--	1.6	--	1.3	--	4.2	7.0	--	--	--	5.0	2.4	A	IB	L	Fair		
58	3.706	L2	Y	1.2	--	--	--	--	--	--	1.9	--	1.6	--	4.7	8.0	--	--	--	--	3.0	A	II	L	Fair		
59	3.706	L3	Y	--	1.0	--	1.3	--	--	--	--	--	1.5	--	3.8	12.0	--	--	--	--	3.8	A	II	M	Poor		
60	3.892	R1	N	2.0	--	--	--	--	--	--	1.3	--	--	--	3.3	0.0	--	7.5	--	--	2.0	B	II	M	Fair		
61	4.060	L1	Y	1.1	--	--	--	--	--	--	1.5	2.0	--	--	4.6	14.5	--	--	--	--	1.6	B	II	M	Fair		
62	4.162	R3	N	--	1.0	--	--	1.0	--	--	0.5	--	2.2	--	4.7	9.0	--	--	--	--	4.7	B	II	M	Poor		
63	4.162	R2	Y	1.4	--	--	--	--	--	--	1.5	--	1.2	--	4.1	8.5	--	--	--	--	2.4	B	II	M	Fair		
64	4.162	R1	Y	1.4	--	--	--	--	--	--	1.4	--	1.3	--	4.1	8.5	--	--	--	--	1.3	A	II	M	Poor		
65	4.162	L1	Y	1.4	--	--	--	--	--	--	0.5	--	1.5	--	3.4	8.5	--	--	--	--	--	--	--	--	Fair		
66	4.162	L2	Y	1.4	--	--	--	--	--	--	1.0	--	1.7	--	4.1	9.0	--	--	--	--	3.0	C	II	M	Fair		
67	4.162	L3	Y	0.7	--	--	--	--	--	1.2	--	0.5	--	1.2	--	3.6	10.0	--	--	--	--	--	--	--	Fair		
68	4.236	R1	Y	1.1	--	--	--	--	--	--	0.6	--	2.0	--	3.7	8.0	--	--	--	--	1.0	A	IB	L	Fair		
69	4.392	L1	Y	1.4	--	--	--	--	--	0.8	0.7	--	1.7	--	4.6	5.0	--	--	--	--	--	--	--	--	Fair		
																									Left Turn Lane		
																									Left Turn Lane		

PAVEMENT EVALUATION CORING AND CONDITION DATA

Cored by:	C. Malone, P. Griffith				Dates Cored:	6/30/19 - 7/3/19			Page:	3	of	15	Typical Section No.:	1																
W.P.I. No.:	Name: 55								Lanes:	6																				
Fin. Proj. ID:	From: SR 682 / 54th Ave S								Shoulder Type and Condition:	Curb																				
F.A. Proj. No.:	To: 22nd Ave N								Inside:																					
County:	Beg MP: 0.867 End MP: 5.878 Lgth: 5.011								Outside:																					
Median Curbed (Y / N):	N	Paved	Lawn	Other:	Vegetation								Curb & Gutter (Y / N):	Y																
Core No.	Mile Post or Sta. No.	Lane	Wheel Path	Pavement Layer (in.)										Base		Subgrade	Crack		Pvmt Cond	Rept	CS	Comments								
				F125	F95	FC5	SP 125	SP 9.5	SP2F	T1	S	S2	BIND	SBRM	RAP	Core Lgth (in.)	Limerock	Shell	A B C	Stabilized Concrete	Depth (in.)	Type	Class	Extent (%)	(in.)	(%)				
70	4.482	R1	Y	1.5	--	--	--	--	1.0	1.0	--	1.8	--	--	5.3	12.0	--	--	--	--	--	--	Fair				Left Turn Lane			
71	4.548	R3	Y	1.8	--	--	--	--	--	0.8	--	1.6	--	--	4.2	10.0	--	--	--	3.0	A	III	S	Poor						
72	4.548	R2	Y	1.4	--	--	--	--	--	1.4	--	1.6	--	--	4.4	6.0	--	--	--	--	--	--	--	Fair						
73	4.548	R1	Y	1.3	--	--	--	--	--	1.3	--	1.3	--	--	3.9	7.3	--	--	--	--	--	--	--	Poor						
74	4.548	L1	Y	1.6	--	--	--	--	--	--	0.6	1.8	--	--	4.0	8.0	--	--	--	7.0	--	--	--	Fair						
75	4.548	L2	Y	1.4	--	--	--	--	--	1.2	--	1.5	--	--	4.1	9.5	--	--	--	--	2.2	A	II	M	Poor					
76	4.548	L3	Y	2.0	--	--	--	--	--	0.8	--	1.1	--	--	3.9	12.0	--	--	--	--	3.1	A	IB	M	Fair					
77	4.651	L1	Y	1.1	--	--	--	--	2.9	--	--	--	--	--	4.0	11.0	--	--	--	--	4.0	B	II	M	Poor				Left Turn Lane	
78	4.746	R1	Y	1.2	--	--	--	--	--	--	1.2	2.0	--	--	4.4	16.0	--	--	--	--	1.9	A	II	M	Fair				Left Turn Lane	
79	4.887	R3	Y	1.9	--	--	--	--	--	0.3	--	1.4	--	--	3.6	10.0	--	--	--	--	3.6	A	II	S	Poor					
80	4.906	L1	Y	1.0	--	--	--	--	1.3	--	0.4	1.9	--	--	4.6	13.5	--	--	--	--	3.3	B	II	L	Fair				Left Turn Lane	
81	5.050	R1	Y	--	1.2	--	--	--	0.8	1.5	--	1.2	--	--	4.7	8.0	--	--	--	--	4.7	B	II	M	Poor				Left Turn Lane	
82	5.138	L1	Y	--	1.7	--	--	--	--	--	--	--	--	--	1.7	--	3.4	12.0	--	--	--	--	--	--	--	Poor				Left Turn Lane
83	5.221	R3	Y	--	1.4	--	--	--	--	0.5	--	1.6	--	--	3.5	9.0	--	--	--	--	3.5	B	II	M	Poor					
84	5.221	R2	Y	1.3	--	--	--	--	--	0.6	--	1.4	--	--	3.3	8.0	--	--	--	--	3.3	A	II	M	Fair					
85	5.221	R1	Y	1.4	--	--	--	--	--	1.2	--	1.5	--	--	4.1	10.5	--	--	--	--	--	--	--	--	Fair					
86	5.221	L1	Y	1.3	--	--	--	--	--	1.6	--	1.3	--	--	4.2	7.5	--	--	--	5.0	--	--	--	--	Fair					
87	5.221	L2	Y	1.2	--	--	--	--	--	1.2	--	1.5	--	--	3.9	7.0	--	--	--	--	--	--	--	--	Fair					
88	5.221	L3	Y	1.7	--	--	--	--	--	0.7	--	1.0	--	--	3.4	6.0	--	--	--	--	1.7	A	II	S	Fair					
89	5.241	R1	Y	1.2	--	--	--	--	--	1.4	--	1.3	--	--	3.9	16.0	--	--	--	--	3.9	B	III	L	Poor				Left Turn Lane	
90	5.325	L1	Y	1.2	--	--	--	--	--	1.4	0.6	1.4	--	--	4.6	15.0	--	--	--	--	--	--	--	--	Fair				Left Turn Lane	
91	5.421	R1	Y	1.0	--	--	2.8	--	--	--	--	--	--	--	3.8	0.0	--	--	2.0	--	--	--	--	--	--	Fair				Left Turn Lane
92	5.523	L1	Y	1.3	--	--	--	--	--	1.3	0.7	1.1	--	--	4.4	9.0	--	--	--	--	--	--	--	--	Fair				Left Turn Lane	
93	5.641	L1	Y	1.5	--	--	1.3	--	--	--	7.7	--	--	--	10.5	0.0	--	2.9	--	--	--	--	--	--	Fair				Left Turn Lane	
94	5.663	R3	Y	1.5	--	--	0.6	--	--	4.0	--	--	--	--	6.1	0.0	--	5.3	--	--	--	--	--	--	Fair					
95	5.663	R2	Y	1.4	--	--	--	--	--	1.3	--	1.4	--	--	4.1	10.0	--	--	--	--	4.1	C	II	S	Poor					
96	5.663	R1	Y	1.1	--	--	--	--	--	1.2	--	1.5	--	--	3.8	8.0	--	--	--	--	--	--	--	--	Fair					
97	5.663	L1	Y	0.8	--	--	1.6	--	--	--	--	1.1	--	--	3.5	9.0	--	--	--	--	--	--	--	--	Fair					
98	5.663	L2	Y	--	0.9	--	--	1.6	--	--	0.9	--	1.7	--	--	5.1	6.5	--	--	--	--	--	--	--	Fair					
99	5.663	L3	Y	1.0	--	--	1.6	--	--	--	0.3	0.6	--	--	3.5	0.0	--	7.3	--	--	--	--	--	--	Fair					
100	5.793	L1	Y	1.0	--	--	--	--	--	2.0	--	--	--	--	3.0</td															

PAVEMENT EVALUATION CORING AND CONDITION DATA

Cored by:	C. Malone, P. Griffith				Dates Cored:	6/30/19 - 7/3/19			Page:	4	of	15	Typical Section No.:	1														
W.P.I. No.:								Name:	55					Lanes:	6													
Fin. Proj. ID:	440246-1							From:	SR 682 / 54th Ave S					Shoulder Type and Condition:	Curb													
F.A. Proj. No.:								To:	22nd Ave N					Inside:														
County:	Pinellas							Beg MP:	0.867	End MP:	5.878	Lgth:	5.011	Outside:														
Median Curbed (Y / N):	N	Paved	Lawn	Other:	Vegetation								Curb & Gutter (Y / N):	Y														
Core No.	Mile Post or Sta. No.	Lane	W h e e l P a t h	Pavement Layer (in.)										Base			Subgrade	Crack			P v m t C o n d	D R e u p t h (in.)	C S r I o o s p s e (%)	Comments				
				F125	F95	FC5	SP 125	SP 9.5	SP2F	T1	S	S2	BIND	SBRM	RAP	Core Lgth (in.)	L i m e r o c k	S H E L L	A B C	C o n c r e t e					S t a b i l i z e d (in.)	D e p t h T y p e	C l a s s	E x t e n t
105	2.845	R1	Y	0.8	--	--	--	--	0.9	0.9	2.4	--	--	5.0	16.0	--	--	--	--	--	--	--	Fair			Left Turn Lane		
106	3.336	R1	N	--	--	1.2	--	--	--	--	1.6	1.1	--	--	3.9	10.0	--	--	--	--	1.2	B	III	S	Poor			Left Turn Lane