


Pavement Conditions

THE FOLLOWING PICTURES ARE EXAMPLES OF SOME OF THE PAVEMENT CONDITIONS SPECIFIED IN SECTION 338.


RAVELING - The progressive separation of aggregate particles in a pavement from the surface downward or from the edges inward.



Blowup of raveled area

**Example photograph of raveling
that would require remedial action
per table 338-1**

BLEEDING - The upward movement of liquid asphalt resulting in the formation of a film of asphalt on the surface.



SLIPPAGE- The movement between layers when none should exist. Picture illustrates classical U pattern.



POT HOLES



DELAMINATION



